

VILLAGE OF COLD SPRING  
 TREE LOCATION AND PRUNING SPECS  
 for  
 REQUEST FOR PROPOSAL  
 Professional Services: Tree Maintenance

Please contact our Tree Advisory Board at [jzwarich.cstab@gmail.com](mailto:jzwarich.cstab@gmail.com) with questions.

CATEGORY	ADJACENT ADDRESS	SPECIES/DBH	PRUNING SPEC
1	210 Main St	Platanus/8"	Reduce competing leader to slow growth and help correct lean. Remove lowest branch over sidewalk (4" diameter).
1	204 Main St	Tillia/10"	Remove four stubs. Remove one 5" crossing branch and one 2" crossing branch and prune 5" bent leader to promote better structure. Selectively remove epicormic growth, leave some to form new structure.
1	107 Main St	Gleditsia/8"	Directional prune to maintain building clearance and to raise canopy on street side to 14'.
1	81 Main St Left	Gleditsia/6"	Directional pruning to maintain building clearance.
1	81 Main St Right	Gleditsia/6"	Directional pruning to maintain building clearance.
1	68 Main St	Acer/Norway/12"	Remove deadwood to reduce risk to pedestrians.
1	61 Main St	Acer/Norway/12"	Directional pruning to maintain building clearance.

2	212 Main St	Platanus/ 14"	Directional prune to maintain 14' clearance as tree grows over street side.
2	210 Main St	Tillia/14"	Remove crossing 4' branch on main leader. Directional prune to maintain 14' clearance as tree grows over street side.
2	204 Main St	Tillia/13"	Corrective of damage. Remove eight stubs and epicormic growth. Remove two 4" hangers and additional minor deadwood.
2	224 Main St Right	Acer/Norway/28"	Remove dead wood and stubs. Thin canopy interior to improve structure.
2	3 Main St	Acer/24"	Reduce weight on main leader over building to mitigate risk. Remove stubs.
2	10 Main St	Acer/22"	Reduce weight on main leader over building to mitigate risk.
2	50 Main St	Acer/Norway/15"	Remove dead branch to maintain safety.
2	113 Main	Gleditsia/15"	Remove deadwood. Raise canopy on street side to maintain 14' clearance.
2	116 Main St	Quercus/14"	Remove 4" damaged limb on sidewalk side. Remove minor deadwood. Remove minor interior crossing branches to promote structure.
2	133 Main St	Tillia/14"	Correct improper pruning on building-side.
2	137 Main	Silver Maple/16"	Remove stub.

2	153 Main St	Zelkova/22"	Directional prune to maintain building clearance.
3	172 Main St	Acer/Norway/28"	Remove large dead limb. Thin crown by 10% to improve wind damage resistance.
3	224 Main St Front	Acer/Norway/32"	Prune to improve structure and reduce breakage risk for 12" lateral branch to east. REMOVE crossing branches interior. Thin canopy by 10%. Directional prune to maintain 14' clearance over street.
3	30 Mountain Ave	Sugar Maple/27"	Remove significant deadwood above 1" diameter. Reduce length of street-side 12" leader to reduce load at trunk. Crown thinning to reduce breakage risk.